400 Seventh Street, S.W.
Washington, D.C. 20590

U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***

U.S. Department of Transportation
National Highway Traffic Safety Administration

CASE SUMMARY

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

PSU 02 CASE NO. 051C TYPE OF ACCIDENT Car hits car

A. DESCRIPTION OF THE ACCIDENT SEQUENCE AND ACCIDENT PECULIARITIES

(Provide a summary of the accident sequence as well as any particular event of the accident that is noteworthy. Injury mechanism and vehicle crashworthiness is the focus, not driver culpability. **Do not include any personal identifiers.** Use reverse side if needed.)

Both Vehicles NB on I87 - four lane divided highway, Two lanes each direction. V1 in passing lane, V2 in driving lane. V1 moves into driving lane, striking V2 in left side, V1 looses control and rolls over on Right shoulder of roadway, V2 goes off Left shoulder down embankment.

B. VEHICLE PROFILE(S)

Vehicle No.	Class of Vehicle	Year/Make/Model	Most Severe Damage		Component Failure
			Damage Plane	Severity Description	
1	Compact	85 Totoya Camry	Top	Moderate	none
2	Compact	86 Mazda323	Left	unk	unk

C. PERSON PROFILE(S)

Vehicle No.	Person Role	Seat Position	Restraint Use	Most Severe Injury			
				Body Region	Lesion	AIS	Injury Source
1	Driver	Lf	La/shoul	Wrist	Comm Fx	2	Shift lever
1	Pass	Rf	La/shoul	Arm	contusion	1	dash
2	Driver	Lf	La/shoul	none			
2	Pass	Rf	La/shoul	none			

DO NOT SANITIZE THIS FORM

HS Form 434A
1/88

U.S. Department of Transportation
National Highway Traffic Safety Administration

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

ACCIDENT COLLISION DIAGRAM

PSU No. 02

Case Number – Stratum 05 1 C



HS Form 431B
1/88

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT COLLISION MEASUREMENT TABLE

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Primary Sampling Unit Number 02 Case Number – Stratum 0516

ACCIDENT COLLISION DIAGRAM

LEVEL I
PHYSICAL EVIDENCE ABSENT

To be accomplished when there is no physical evidence present at the scene:

*approximate vehicle orientation at impact and final rest

*applicable road/roadway delineation (e.g., curbs/edge lines, lane markings, median markings, pavement markings, etc.)

*applicable traffic controls (e.g., speed limit)

*north arrow placed on diagram

*sketch required

LEVEL II
PHYSICAL EVIDENCE PRESENT

In addition to the Level I tasks noted above, the following must be accomplished when physical evidence is present:

*document reference point and reference line relative to physical features present at the scene

*scaled documentation of all accident induced physical evidence

*scaled documentation of all roadside objects contacted

*roadway surface type and condition of applicable roadways

*grade measurements for all applicable roadways

*scaled representations of the vehicle(s) at pre-impact, impact, and final rest based upon either:

a) physical evidence, or

b) reconstructed accident dynamics

CRASH DATA

	VEH. #1	VEH. #2	VEH. #3
Heading Angle	046	018	
Surface Type	ZIT		
Surface Condition	DRY		
Grade Measurement (v:h)	LEVEL		

Reference Point: _____ Reference Line: _____

Item	Distance and Direction from Reference Point	Distance and Direction from Reference Line
NO EVIDENCE		

HS Form 431A
1/88

Item	Distance and Direction from Reference Point	Distance and Direction from Reference Line

U.S. Department of Transportation
National Highway Traffic Safety Administration

EXTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 02	3. Vehicle Number: 01
2. Case Number–Stratum: 051C	

VEHICLE IDENTIFICATION

VIN JT2SV16E1F[redacted] Model Year 1985

Vehicle Make (specify): Toyota Vehicle Model (specify): Camry LE

LOCATOR

Locate the end of the damage with respect to the vehicle longitudinal center line or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L

CRUSH PROFILE

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure and document on the vehicle diagram the location of maximum crush.

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

Specific Impact Number	Plane of C-Measurements	Direct Damage Width (CDC)	Direct Damage Max Crush	Field L	C_1	C_2	C_3	C_4	C_5	C_6	±D
	Rollover										

HS Form 435A
1/88

VEHICLE DAMAGE SKETCH

TIRE—WHEEL DAMAGE

a. Rotation physically restricted		b. Tire deflated	
RF	2	RF	2
LF	2	LF	2
RR	1	RR	2
LR	2	LR	2

(1) Yes (2) No (8) NA (9) Unk.

TYPE OF TRANSMISSION

☐ Manual ☒ Automatic

ORIGINAL SPECIFICATIONS

Wheelbase	102.4
Overall Length	175.6
Maximum Width	66.5
Curb Weight	2326
Average Track	56.8
Front Overhang	N/A
Rear Overhang	N/A
Engine Size: cyl./ displ.	4 2.0
Undeformed End Width	62.0

WHEEL STEER ANGLES

(For locked front wheels or displaced rear axles only)

RF ± ___ ___ °
LF ± ___ ___ °
RR ± ___ ___ °
LR ± ___ ___ °

Within ±5 degrees

DRIVE WHEELS

☒ FWD ☐ RWD ☐ 4WD

Approximate Cargo Weight 0









Bumper corner 33.0" 101.5" 39" Bumper corner

Stringline N/A " N/A " Stringline



Bumper corner 39.0" 103.5" 31" Bumper corner

Stringline N/A " GRASS/ROCKS IN BEAD N/A " Stringline

NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewall, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CDC WORKSHEET

CODES FOR OBJECT CONTACTED

01-30—Vehicle Number

Noncollision
- (31) Overturn—rollover
- (32) Fire or explosion
- (33) Jackknife
- (34) Other intraunit damage (specify): _____
- (35) Noncollision injury
- (38) Other noncollision (specify): _____
- (39) Noncollision—details unknown

Collision with Fixed Object
- (41) Tree (≤4 inches in diameter)
- (42) Tree (>4 inches in diameter)
- (43) Shrubbery or bush
- (44) Embankment
- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
- (50) Pole or post (≤4 inches in diameter)
- (51) Pole or post (>4 but ≤12 inches in diameter)
- (52) Pole or post (>12 inches in diameter)
- (53) Pole or post (diameter unknown)
- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (specify): _____
- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or Culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____
- (69) Unknown fixed object

Collision With Nonfixed Object
- (71) Motor vehicle not in transport
- (72) Pedestrian
- (73) Cyclist or cycle
- (74) Other nonmotorist or conveyance (specify): _____
- (75) Vehicle occupant
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (88) Other nonfixed object (specify): _____
- (89) Unknown nonfixed object
- (98) Other event (specify): _____
- (99) Unknown event or object

DEFORMATION CLASSIFICATION BY EVENT NUMBER

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force (degrees)	Incremental Value of Shift	(3) Deformation Location	(4) Specific Longitudinal or Lateral Location	(5) Specific Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
01	02	360	00	F	R	E	S	01
02	31	000	00	T	Y	D	0	03

U.S. Department of Transportation
National Highway Traffic Safety Administration

INTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 02
2. Case Number–Stratum: 051C
3. Vehicle Number: 01

INTEGRITY

4. Passenger Compartment Integrity 98

(00) No integrity loss

Yes, Integrity Was Lost Through
(01) Windshield
(02) Door (side)
(03) Door/hatch (rear)
(04) Roof
(05) Roof glass
(06) Side window
(07) Rear window
(08) Roof and roof glass
(09) Windshield and door (side)
(10) Windshield and roof
(11) Side and rear window
(98) Other combination of above (specify):

(99) Unknown

Door, Tailgate Or Hatch Opening

5. LF 1 6. RF 1 7. LR 1 8. RR 1 9. TG/H 0

(0) No door/gate/hatch
(1) Door/gate/hatch remained closed and operational
(2) Door/gate/hatch came open during collision
(3) Door/gate/hatch jammed shut
(8) Other (specify):

(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch Opening in Collision. If IV05-IV09 ≠ 2, Then Code 0.

10. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

(0) No door/gate/hatch or door not opened

Door, Tailgate, or Hatch Came Open During Collision
(1) Door operational (no damage)
(2) Latch/striker failure due to damage
(3) Hinge failure due to damage
(4) Door structure failure due to damage
(5) Door support (i.e., pillar, sill, roof side rail, etc.) failure due to damage
(6) Latch/striker and hinge failure due to damage
(8) Other failure (specify):

(9) Unknown

GLAZING

Glazing Damage from Impact Forces

15. WS 2 16. LF 6 17. RF 6 18. LR 0 19. RR 6
20. BL 6 21. Roof 8 22. Other 6

(0) No glazing damage from impact forces
(2) Glazing in place and cracked from impact forces
(3) Glazing in place and holed from impact forces
(4) Glazing out-of-place (cracked or not) and not holed from impact forces
(5) Glazing out-of-place and holed from impact forces
(6) Glazing disintegrated from impact forces
(7) Glazing removed prior to accident
(8) No glazing
(9) Unknown if damaged

Glazing Damage from Occupant Contact

23. WS 9 24. LF 0 25. RF 0 26. LR 0 27. RR 0
28. BL 0 29. Roof 0 30. Other 0

(0) No occupant contact to glazing or no glazing
(1) Glazing contacted by occupant but no glazing damage
(2) Glazing in place and cracked by occupant contact
(3) Glazing in place and holed by occupant contact
(4) Glazing out-of-place (cracked or not) by occupant contact and not holed by occupant contact
(5) Glazing out-of-place by occupant contact and holed by occupant contact
(6) Glazing disintegrated by occupant contact
(9) Unknown if contacted by occupant

If No Glazing Damage ***And*** No Occupant Contact or No Glazing, Then Code IV 31 Through IV 46 As 0

Type of Window/Windshield Glazing

31. WS 1 32. LF 2 33. RF 2 34. LR 0 35. RR 2
36. BL 2 37. Roof 6 38. Other 2

(0) No glazing contact and no damage, or no glazing
(1) AS-1 – Laminated
(2) AS-2 – Tempered
(3) AS-3 – Tempered-tinted
(4) AS-14 – Glass/Plastic
(8) Other (specify):

(9) Unknown

Window Precrash Glazing Status

39. WS 1 40. LF 2 41. RF 2 42. LR 0 43. RR 2
44. BL 1 45. Roof 0 46. Other 1

(0) No glazing contact and no damage, or no glazing
(1) Fixed
(2) Closed
(3) Partially opened
(4) Fully opened
(9) Unknown

INTRUSION WORK SHEET





	INTRUDED COMPONENT	LOCATION OF INTRUSION	DOMINANT CRUSH DIRECTION	COMPARISON VALUE	–	INTRUDED VALUE	=	INTRUSION	
	A	11	Vert		–		=	3-6"	EST "DIFF
	A	13	Vert		–		=	3-6"	—
3	W/S	11	Vert	39.5	–	30	=	9.5	TO FLOOR
2	W/S	12	Vert	30.5	–	10	=	20.5	TO CONSOLE
1	W/S	13	Vert	39.5	–	13	=	26.5	TO FLOOR
9 10	12, 13, 14	11	Vert	41.0	–	36	=	5	TO FLOOR
	12, - 14	12	Vert	32.0	–	31	=	1	TO CONSOLE
5 6 7	12, 13, 14	13	Vert	41.0	–	35	=	6	TO FLOOR
	WIND FRAME	11	LAT	0	–	5	=	5	
4	"	13	LATERAL	0	–	7	=	7	
					–		=		
					–		=		
					–		=		
					–		=		
					–		=		

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV 47-IV 86 blank.

	Location of Intrusion	Intruding Component	Magnitude of Intrusion	Dominant Crush Direction
1st	47. 13	48. 14	49. 6	50. 1
2nd	51. 12	52. 14	53. 5	54. 1
3rd	55. 11	56. 14	57. 3	58. 1
4th	59. 13	60. 16	61. 3	62. 3
5th	63. 13	64. 12	65. 3	66. 1
6th	67. 13	68. 13	69. 3	70. 1
7th	71. 13	72. 14	73. 3	74. 1
8th	75. 11	76. 12	77. 2	78. 1
9th	79. 11	80. 13	81. 2	82. 1
10th	83. 11	84. 14	85. 2	86. 1

LOCATION OF INTRUSION

Front Seat
- (11) Left
- (12) Middle
- (13) Right

Second Seat
- (21) Left
- (22) Middle
- (23) Right

Third Seat
- (31) Left
- (32) Middle
- (33) Right

Fourth Seat
- (41) Left
- (42) Middle
- (43) Right

(98) Other enclosed area (specify): _____

(99) Unknown

INTRUDING COMPONENT

Interior Components
- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- ✓(06) A-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Door panel
- (11) Side panel/kickpanel
- ✓(12) Roof (or convertible top)
- ✓(13) Roof side rail
- ✓(14) Windshield
- ✓(15) Windshield header
- ✓(16) Window frame
- (17) Floor pan
- (18) Backlight header
- (19) Front seat back
- (20) Second seat back
- (21) Third seat back
- (22) Fourth seat back
- (23) Fifth seat back
- (24) Seat cushion
- (25) Back panel or door surface
- (26) Other interior component (specify): _____

Exterior Components
- (30) Hood
- (31) Outside surface of vehicle (specify): _____
- (32) Other exterior object in the environment (specify): _____
- (33) Unknown exterior object
- (98) Intrusion of unlisted component(s) (specify): _____
- (99) Unknown

MAGNITUDE OF INTRUSION
- (1) ≥ 1 inch but < 3 inches
- (2) ≥ 3 inches but < 6 inches
- (3) ≥ 6 inches but < 12 inches
- (4) ≥ 12 inches but < 18 inches
- (5) ≥ 18 inches but < 24 inches
- (6) ≥ 24 inches
- (9) Unknown

DOMINANT CRUSH DIRECTION
- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (9) Unknown

STEERING COLUMN WORKING DIAGRAMS

STEERING COLUMN COLLAPSE

Steering Column Shear Module Movement





Left ___

Right ___ V = _____"

Direction and Magnitude of Steering Column Movement





Extruder Retainer (Mini Column) or Flared Tube (Mod Column)

E=____

STEERING COLUMN MOVEMENT

Vertical Movement



Lateral Movement



Longitudinal Movement



	COMPARISON VALUE – DAMAGED VALUE = MOVEMENT
VERTICAL	– =
LATERAL	– =
LONGITUDINAL	– =

STEERING RIM/SPOKE DEFORMATION

COMPARISON VALUE –	DAMAGED VALUE =	DEFORMATION
–	=	
–	=	

STEERING COLUMN

87. Steering Column Type 8

(1) Fixed column
(2) Tilt column
(3) Telescoping column
(4) Tilt and telescoping column
(8) Other column type (specify):

_____

(9) Unknown

88. Steering Column Collapse Due to Occupant Loading 00

_____ Code actual measured movement to the nearest inch. See coding manual for measurement technique(s).

(00) No movement, compression, or collapse
(01-49) Actual measured value
(50) 50 inches or greater

Estimated movement from observation
(81) Less than 1 inch
(82) ≥ 1 inch but < 2 inches
(83) ≥ 2 inches but < 4 inches
(84) ≥ 4 inches but < 6 inches
(85) ≥ 6 inches but < 8 inches
(86) Greater than or equal to 8 inches

(97) Apparent movement, value undetermined or cannot be measured or estimated
(98) Nonspecified type column
(99) Unknown

Direction And Magnitude of Steering Column Movement

89. Vertical Movement +06

90. Lateral Movement +00

91. Longitudinal Movement +00

Code the actual measured movement to the nearest inch. See Coding Manual for measurement technique(s)
(+00) No Steering column movement
(±01 – ±49) Actual measured value
(+50) 50 inches or greater

Estimated movement from observation
(±81) ≥ 1 inch but < 3 inches
(±82) ≥ 3 inches but < 6 inches
(±83) ≥ 6 inches but < 12 inches
(±84) ≥ 12 inches

(__97) Apparent movement > 1 inch but cannot be measured or estimated
(__99) Unknown

92. Steering Rim/Spoke Deformation 0

_____ Code actual measured deformation to the nearest inch.
(0) No steering rim deformation
(1-5) Actual measured value
(6) 6 inches or more
(8) Observed deformation cannot be measured
(9) Unknown

93. Location of Steering Rim/Spoke Deformation 00

(00) No steering rim deformation

Quarter Sections
(01) Section A
(02) Section B
(03) Section C
(04) Section D

Half Sections
(05) Upper half of rim/spoke
(06) Lower half of rim/spoke
(07) Left half of rim/spoke
(08) Right half of rim/spoke





(09) Complete steering wheel collapse
(10) Undetermined location
(99) Unknown

INSTRUMENT PANEL

94. Odometer Reading 057,000

56878 **miles – Code mileage to the nearest 1,000 miles**
(000) No odometer
(001) Less than 1,500 miles
(300) 299,500 miles or more
(999) Unknown

Source: _____

95. Instrument Panel Damage from Occupant Contact 0
(0) No
(1) Yes
(9) Unknown

96. Knee Bolsters Deformed from Occupant Contact 8
(0) No
(1) Yes
(8) Not present
(9) Unknown

97. Did Glove Compartment Door Open During Collision(s) 0
(0) No
(1) Yes
(8) Not present
(9) Unknown

VEHICLE INTERIOR SKETCHES



POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	57	01	R/HIP	LEVER BENT	1
B	31	02	R/HIP	BLOOD / OCC TRAJ.	1
C	50/54	01/02	HEAD	BLOOD	2
D	02	01	?	BROKE OFF	3
E					
F					
G					
H					
I					
J					
K					
L					
M					
N					

CODES FOR INTERIOR COMPONENTS

FRONT
- (01) Windshield
- (02) Mirror
- (03) Sunvisor
- (04) Steering wheel rim
- (05) Steering wheel hub/spoke
- (06) Steering wheel (combination of codes 04 and 05)
- (07) Steering column, transmission selector lever, other attachment
- (08) Add on equipment (e.g., CB, tape deck, air conditioner)
- (09) Left instrument panel and below
- (10) Center instrument panel and below
- (11) Right instrument panel and below
- (12) Glove compartment door
- (13) Knee bolster
- (14) Windshield including one or more of the following: front header, A-pillar, instrument panel, mirror,or steering assembly (driver side only)
- (15) Windshield including one or more of the following: front header, A-pillar, instrument panel, or mirror (passenger side only)
- (16) Other front object (specify): _____

LEFT SIDE
- (20) Left side interior surface, excluding hardware or armrests
- (21) Left side hardware or armrest
- (22) Left A pillar
- (23) Left B pillar
- (24) Other left pillar (specify): _____
- (25) Left side window glass or frame
- (26) Left side window glass including one or more of the following: frame, window sill, A-pillar, B-pillar, or roof side rail
- (27) Other left side object (specify): _____

RIGHT SIDE
- (30) Right side interior surface, excluding hardware or armrests
- (31) Right side hardware or armrest
- (32) Right A pillar
- (33) Right B pillar
- (34) Other right pillar (specify): _____
- (35) Right side window glass or frame
- (36) Right side window glass including one or more of the following: frame, window sill, A-pillar, B-pillar, or roof side rail
- (37) Other right side object (specify): _____

INTERIOR
- (40) Seat, back support
- (41) Belt restraint webbing/buckle
- (42) Belt restraint B-pillar attachment point
- (43) Other restraint system component (specify): _____
- (44) Head restraint system
- (45) Air cushion
- (46) Other occupants (specify): _____
- (47) Interior loose objects
- (48) Child safety seat (specify): _____
- (49) Other interior object (specify): _____

ROOF
- (50) Front header
- (51) Rear header
- (52) Roof left side rail
- (53) Roof right side rail
- (54) Roof or convertible top

FLOOR
- (56) Floor including toe pan
- (57) Floor or console mounted transmission lever, including console
- (58) Parking brake handle
- (59) Foot controls including parking brake

REAR
- (60) Backlight (rear window)
- (61) Backlight storage rack, door, etc.
- (62) Other rear object (specify): _____

CONFIDENCE LEVEL OF CONTACT POINT
- (1) Certain
- (2) Probable
- (3) Possible
- (4) Unknown

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attributes for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	Availability			
	Function			
	Failure			

Automatic (Passive) Restraint System Availability

(0) Not equipped/not available
(1) Airbag
(2) Airbag disconnected (specify):

_____

(3) Airbag not reinstalled
(4) 2 point automatic belts
(5) 3 point automatic belts
(6) Automatic belts destroyed or rendered inoperative
(9) Unknown

Automatic (Passive) Restraint Function

(0) Not equipped/not available

Automatic Belt
(1) Automatic belt in use
(2) Automatic belt not in use
(3) Automatic belt use unknown

Air Bag
(4) Airbag deployed during accident
(5) Airbag deployed inadvertently just prior to accident
(6) Deployed, accident sequence undetermined
(7) Nondeployed
(8) Unknown if deployed
(9) Unknown

Did Automatic (Passive) Restraint Fail

(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(9) Unknown

MANUAL RESTRAINTS

NOTES: Encode the applicable data **for each seat position** in the vehicle. The attributes for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a child safety seat is present, encode the data on the back of this page.

If the vehicle has automatic restraints available, encode the appropriate data on the back of the previous page.

		Left	Center	Right
FIRST	Availability	4	—	4
	Use	04	—	04
	Failure Modes	/	—	/
SECOND	Availability	3	3	3
	Use	00	00	00
	Failure Modes	0	0	0
THIRD	Availability			
	Use			
	Failure Modes			
OTHER	Availability			
	Use			
	Failure Modes			

Manual (Active) Belt System Availability

(0) Not available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available – type unknown
(8) Other belt (specify):

_____

(9) Unknown

Manual (Active) Belt System Use

(00) None used, not available, or belt removed/destroyed
(01) Inoperative (specify):

_____

(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used – type unknown

_____

(08) Other belt used (specify):

_____

(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat – type unknown
(18) Other belt used with child safety seat (specify):

_____

(99) Unknown if belt used

Manual (Active) Belt Failure Modes During Accident

(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Manual belt failure(s) (encode all that apply above)
[A] Torn webbing (stretched webbing not included)
[B] Broken buckle or latchplate
[C] Upper anchorage separated
[D] Other achorage separated (specify):

_____

[E] Broken retractor
[F] Other manual belt failure (specify):

_____

(9) Unknown

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

1. Type of Child Safety Seat

(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat
(7) Other type child safety seat (specify):

_____

(8) Unknown child safety seat type
(9) Unknown if child safety seat used

2. Child Safety Seat Orientation

(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(03) Other orientation (specify):

_____

(04) Unknown orientation

Designed for Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify):

_____

(19) Unknown orientation

Unknown Design or Orientation for This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify):

_____

(29) Unknown orientation

(99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

4. Child Safety Seat Shield Usage

5. Child Safety Seat Tether Usage

Note: Options Below Are Used for Variables 3-5.

(00) No child safety seat

Not Designed with Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed with Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown if Designed with Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

6. Child Safety Seat Make/Model
(Specify make/model and occupant number)

_____

_____

_____

_____

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for **each seat position** in the vehicle. The attributes for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	Head Restraint Type/Damage	3	—	3
	Seat Type	02	—	02
	Seat Performance	1	—	1
SECOND	Head Restraint Type/Damage	1	0	1
	Seat Type	03	03	03
	Seat Performance	0	0	0
THIRD	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
OTHER	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			

Head Restraint Type/Damage by Occupant at This Occupant Position

(0) No head restraints
(1) Integral — no damage
(2) Integral — damaged during accident
(3) Adjustable — no damage
(4) Adjustable — damaged during accident
(5) Add-on — no damage
(6) Add-on — damaged during accident
(8) Other (specify): _____
(9) Unknown

Seat Type (This Occupant Position)

(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., van type)
(09) Other seat type (specify): _____
(99) Unknown

Seat Performance (This Occupant Position)

(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat performance failure(s)
(Encode all that apply)

[A] Seat adjusters failed
[B] Seat back folding locks failed
[C] Seat tracks failed
[D] Seat anchors failed
[E] Deformed by impact of passenger from rear
[F] Deformed by impact of passenger from front
[G] Deformed by own inertial forces
[H] Deformed by passenger compartment intrusion
(specify):

_____
_____
_____

[I] Other (specify): _____
_____

(9) Unknown

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE (I.E. UNUSUAL OCCUPANT CONTACT PATTERN)

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indications that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No [✓] Yes [ ]

Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number						
Ejection						
Ejection Area						
Ejection Medium						
Medium Status						

Ejection
(1) Complete ejection
(2) Partial ejection
(3) Ejection, unknown degree
(9) Unknown

Ejection Area
(1) Windshield
(2) Left front
(3) Right front
(4) Left rear
(5) Right rear
(6) Rear
(7) Roof
(8) Other area (e.g., back of pickup, etc.) (specify): _____
(9) Unknown

Ejection Medium
(1) Door/hatch/tailgate
(2) Nonfixed roof structure
(3) Fixed glazing
(4) Nonfixed glazing (specify): _____
(5) Integral structure
(8) Other medium (specify): _____
(9) Unknown

Medium Status (Immediately Prior to Impact)
(1) Open
(2) Closed
(3) Integral structure
(9) Unknown

ENTRAPMENT No [✓] Yes [ ]

Describe entrapment mechanism: _____

Component(s): _____

(Note in vehicle interior diagram)

U.S. Department of Transportation

National Highway Traffic Safety Administration

OCCUPANT INJURY FORM

Form Approved
O.M.B. No. 2127-0021
NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 02
2. Case Number–Stratum: 051C
3. Vehicle Number: 01
4. Occupant Number: 01

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than twenty injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	O.I.C.–A.I.S. Body Region	Aspect	Lesion	System Organ	A.I.S. Severity	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion No.
1st	5. 2	6. W	7. R	8. F	9. S	10. 2	11. 37	12. 2	13. 1	14. 00
2nd	15. 2	16. E	17. W	18. L	19. E	20. 1	21. 91	22. 2	23. 3	24. 00
3rd	25. 2	26. N	27. P	28. I	29. M	30. 1	31. 92	32. 3	33. 3	34. 00
4th	35. 2	36. C	37. U	38. C	39. E	40. 1	41. 04	42. 3	43. 1	44. 00
5th	45. 2	46. S	47. L	48. C	49. E	50. 1	51. 20	52. 3	53. 1	54. 00
6th	55. 2	56. H	57. U	58. C	59. E	60. 1	61. 54	62. 3	63. 1	64. 08
7th	65. 2	66. N	67. U	68. C	69. E	70. 1	71. 97	72. 9	73. 7	74. 99
8th	75. 2	76. B	77. U	78. C	79. E	80. 1	81. 54	82. 3	83. 1	84. 08
9th	85. 2	86. R	87. R	88. A	89. E	90. 1	91. 57	92. 3	93. 1	94. 00
10th	95.	96.	97.	98.	99.	100.	101.	102.	103.	104.
11th	105.	106.	107.	108.	109.	110.	111.	112.	113.	114.
12th	115.	116.	117.	118.	119.	120.	121.	122.	123.	124.
13th	125.	126.	127.	128.	129.	130.	131.	132.	133.	134.
14th	135.	136.	137.	138.	139.	140.	141.	142.	143.	144.
15th	145.	146.	147.	148.	149.	150.	151.	152.	153.	154.
16th	155.	156.	157.	158.	159.	160.	161.	162.	163.	164.
17th	165.	166.	167.	168.	169.	170.	171.	172.	173.	174.
18th	175.	176.	177.	178.	179.	180.	181.	182.	183.	184.
19th	185.	186.	187.	188.	189.	190.	191.	192.	193.	194.
20th	195.	196.	197.	198.	199.	200.	201.	202.	203.	204.

OCCUPANT INJURY DATA SUPPLEMENT

	Source of Injury Data	O.I.C.–A.I.S. Body Region	Aspect	Lesion	System Organ	A.I.S. Severity	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion No.
21st										
22nd										
23rd										
24th										
25th										
26th										
27th										
28th										
29th										
30th										
31st										
32nd		Interview								
33rd		(R) CURIST		BROKEN		SHIFT LOWER				
34th		(L) Shoulder		Bruised		(L) DOOR				
35th		Neck		Bruised		Impact				
36th		Head		Bruised/Cut		Roof				
37th		BACK		Bruised		Impact				
38th										
39th										
40th										
41st										
42nd										
43rd										
44th										
45th										

OFFICIAL INJURY DATA – SOFT TISSUE INJURIES

Indicate the *Location, Lesion, Detail* (size, depth, fracture type, head injury clinical signs and neurological deficits), and *Source* of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



SOURCE OF INJURY DATA

OFFICIAL

(1) Autopsy records with or without hospital medical records
(2) Hospital medical records other than emergency room (eg. discharge summary)
(3) Emergency room records only (including associated X-rays or other lab reports)
(4) Private physician, walk-in or emergency clinic

UNOFFICIAL

(5) Lay coroner report
(6) E.M.S. personnel
(7) Interviewee
(8) Other source (specify):

(9) Police

INJURY SOURCE

FRONT

(01) Windshield
(02) Mirror
(03) Sunvisor
(04) Steering wheel rim
(05) Steering wheel hub/spoke
(06) Steering wheel (combination of codes 04 and 05)
(07) Steering column, transmission selector lever, other attachment
(08) Add-on equipment (e.g., CB, tape deck, air conditioner)
(09) Left instrument panel and below
(10) Center instrument panel and below
(11) Right instrument panel and below
(12) Glove compartment door
(13) Knee bolster
(14) Windshield including one or more of the following: front header, A-pillar, instrument panel, mirror, or steering assembly (driver side only)
(15) Windshield including one or more of the following: front header, A-pillar, instrument panel, or mirror (passenger side only)
(16) Other front object (specify):

LEFT SIDE

(20) Left side interior surface, excluding hardware or armrests
(21) Left side hardware or armrest
(22) Left A pillar
(23) Left B pillar
(24) Other left pillar (specify):

(25) Left side window glass or frame
(26) Left side window glass including one or more of the following: frame, window sill, A-pillar, B-pillar, or roof side rail
(27) Other left side object (specify):

RIGHT SIDE

(30) Right side interior surface, excluding hardware or armrests
(31) Right side hardware or armrest
(32) Right A pillar
(33) Right B pillar
(34) Other right pillar (specify):

(35) Right side window glass or frame
(36) Right side window glass including one or more of the following: frame, window sill, A-pillar, B-pillar, roof side rail
(37) Other right side object (specify):

INTERIOR

(40) Seat, back support
(41) Belt restraint webbing/buckle
(42) Belt restraint B-pillar attachment point
(43) Other restraint system component (specify):

(44) Head restraint system
(45) Air cushion
(46) Other occupants (specify):

(47) Interior loose objects
(48) Child safety seat (specify):

(49) Other interior object (specify):

ROOF

(50) Front header
(51) Rear header
(52) Roof left side rail
(53) Roof right side rail
(54) Roof or convertible top

FLOOR

(56) Floor including toe pan
(57) Floor or console mounted transmission lever, including console
(58) Parking brake handle
(59) Foot controls including parking brake

REAR

(60) Backlight (rear window)
(61) Backlight storage rack, door, etc.
(62) Other rear object (specify):

EXTERIOR OF OCCUPANT'S VEHICLE

(65) Hood
(66) Outside hardware (e.g., outside mirror, antenna)
(67) Other exterior surface or tires (specify):

(68) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE

(70) Front bumper
(71) Hood edge
(72) Other front of vehicle (specify):

(73) Hood
(74) Hood ornament
(75) Windshield, roof rail, A-pillar
(76) Side surface
(77) Side mirrors
(78) Other side protrusions (specify):

(79) Rear surface
(80) Undercarriage
(81) Tires and wheels
(82) Other exterior of other motor vehicle (specify):

(83) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT

(84) Ground
(85) Other vehicle or object (specify)

(86) Unknown vehicle or object

NONCONTACT INJURY

(90) Fire in vehicle
(91) Flying glass
(92) Other noncontact injury source (specify)

(97) Injured, unknown source

INJURY SOURCE CONFIDENCE LEVEL

(1) Certain
(2) Probable
(3) Possible
(9) Unknown

DIRECT/INDIRECT INJURY

(1) Direct contact injury
(2) Indirect contact injury
(3) Noncontact injury
(7) Injured, unknown source

OCCUPANT INJURY CLASSIFICATION

O.I.C. Body Region

(M) Abdomen
(Q) Ankle–foot
(A) Arm (upper)
(B) Back–thoracolumbar spine
(C) Chest
(E) Elbow
(F) Face
(R) Forearm
(H) Head–skull
(U) Injured, unknown region
(K) Knee
(L) Leg (lower)
(Y) Lower limb(s) (whole or unknown part)
(N) Neck–cervical spine
(P) Pelvic–hip
(S) Shoulder
(T) Thigh
(X) Upper limb(s) (whole or unknown part)
(O) Whole body
(W) Wrist–hand

Aspect of Injury

(A) Anterior–front
(C) Central
(I) Inferior–lower
(U) Injured, unknown aspect
(L) Left
(P) Posterior–back
(R) Right
(S) Superior–upper
(W) Whole region

Lesion

(A) Abrasion
(M) Amputation
(V) Avulsion
(B) Burn
(K) Concussion
(C) Contusion
(N) Crush
(G) Detachment, separation
(D) Dislocation
(F) Fracture
(Z) Fracture and dislocation
(U) Injured, unknown lesion
(L) Laceration
(O) Other
(P) Perforation, puncture
(R) Rupture
(S) Sprain
(T) Strain
(E) Total severance, transection

System/Organ

(W) All systems in region
(A) Arteries–veins
(B) Brain
(D) Digestive
(E) Ears
(O) Eye
(H) Heart
(U) Injured, unknown system
(I) Integumentary
(J) Joints
(K) Kidneys
(L) Liver
(M) Muscles
(N) Nervous system
(P) Pulmonary–lungs
(R) Respiratory
(S) Skeletal
(C) Spinal cord
(Q) Spleen
(T) Thyroid, other endocrine gland
(G) Urogenital
(V) Vertebrae

Abbreviated Injury Scale

(1) Minor injury
(2) Moderate injury
(3) Serious injury
(4) Severe injury
(5) Critical injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

OFFICIAL INJURY DATA – SKELETAL INJURIES

Indicate the *Location, Lesion, Detail* (size, depth, fracture type, head injury clinical signs and neurological deficits), and *Source* of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



OFFICIAL INJURY DATA – INTERNAL INJURIES

Indicate the *Location, Lesion, Detail* (size, depth, fracture type, head injury clinical signs and neurological deficits), and *Source* of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





U.S. Department of Transportation

National Highway Traffic Safety Administration

Form Approved
O.M.B. No. 2127-0021
NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

OCCUPANT INJURY FORM

1. Primary Sampling Unit Number: 02
2. Case Number–Stratum: 051C
3. Vehicle Number: 01
4. Occupant Number: 02

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than twenty injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	O.I.C.–A.I.S. Body Region	Aspect	Lesion	System Organ	A.I.S. Severity	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion No.
1st	5. 2	6. X	7. R	8. C	9. I	10. 1	11. 11	12. 3	13. 1	14. 00
2nd	15. 3	16. W	17. R	18. L	19. I	20. 1	21. 91	22. 3	23. 3	24. 00
3rd	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.
4th	35.	36.	37.	38.	39.	40.	41.	42.	43.	44.
5th	45.	46.	47.	48.	49.	50.	51.	52.	53.	54.
6th	55.	56.	57.	58.	59.	60.	61.	62.	63.	64.
7th	65.	66.	67.	68.	69.	70.	71.	72.	73.	74.
8th	75.	76.	77.	78.	79.	80.	81.	82.	83.	84.
9th	85.	86.	87.	88.	89.	90.	91.	92.	93.	94.
10th	95.	96.	97.	98.	99.	100.	101.	102.	103.	104.
11th	105.	106.	107.	108.	109.	110.	111.	112.	113.	114.
12th	115.	116.	117.	118.	119.	120.	121.	122.	123.	124.
13th	125.	126.	127.	128.	129.	130.	131.	132.	133.	134.
14th	135.	136.	137.	138.	139.	140.	141.	142.	143.	144.
15th	145.	146.	147.	148.	149.	150.	151.	152.	153.	154.
16th	155.	156.	157.	158.	159.	160.	161.	162.	163.	164.
17th	165.	166.	167.	168.	169.	170.	171.	172.	173.	174.
18th	175.	176.	177.	178.	179.	180.	181.	182.	183.	184.
19th	185.	186.	187.	188.	189.	190.	191.	192.	193.	194.
20th	195.	196.	197.	198.	199.	200.	201.	202.	203.	204.

OCCUPANT INJURY DATA SUPPLEMENT

	Source of Injury Data	O.I.C. – A.I.S.					Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion No.
		Body Region	Aspect	Lesion	System Organ	A.I.S. Severity				
21st	—	—	—	—	—	—	— —	—	—	— —
22nd	—	—	—	—	—	—	— —	—	—	— —
23rd	—	—	—	—	—	—	— —	—	—	— —
24th	—	—	—	—	—	—	— —	—	—	— —
25th	—	—	—	—	—	—	— —	—	—	— —
26th	—	—	—	—	—	—	— —	—	—	— —
27th	—	—	—	—	—	—	— —	—	—	— —
28th	—	—	—	—	—	—	— —	—	—	— —
29th	—	—	—	—	—	—	— —	—	—	— —
30th	—	—	—	—	—	—	— —	—	—	— —
31st	—	—	—	—	—	—	— —	—	—	— —
32nd	—	—	—	—	—	—	— —	—	—	— —
33rd	—	—	—	—	—	—	— —	—	—	— —
34th	—	—	—	—	—	—	— —	—	—	— —
35th	—	—	—	—	—	—	— —	—	—	— —
36th	—	—	—	—	—	—	— —	—	—	— —
37th	—	—	—	—	—	—	— —	—	—	— —
38th	—	—	—	—	—	—	— —	—	—	— —
39th	—	—	—	—	—	—	— —	—	—	— —
40th	—	—	—	—	—	—	— —	—	—	— —
41st	—	—	—	—	—	—	— —	—	—	— —
42nd	—	—	—	—	—	—	— —	—	—	— —
43rd	—	—	—	—	—	—	— —	—	—	— —
44th	—	—	—	—	—	—	— —	—	—	— —
45th	—	—	—	—	—	—	— —	—	—	— —

INT

① R-hand. Cut dash

② Forearm Cut DASH

OFFICIAL INJURY DATA—SOFT TISSUE INJURIES

Indicate the *Location, Lesion, Detail* (size, depth, fracture type, head injury clinical signs and neurological deficits), and *Source* of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





SOURCE OF INJURY DATA

OFFICIAL

(1) Autopsy records with or without hospital medical records
(2) Hospital medical records other than emergency room (eg. discharge summary)
(3) Emergency room records only (including associated X-rays or other lab reports)
(4) Private physician, walk-in or emergency clinic

UNOFFICIAL

(5) Lay coroner report
(6) E.M.S. personnel
(7) Interviewee
(8) Other source (specify):

(9) Police

INJURY SOURCE

FRONT

(01) Windshield
(02) Mirror
(03) Sunvisor
(04) Steering wheel rim
(05) Steering wheel hub/spoke
(06) Steering wheel (combination of codes 04 and 05)
(07) Steering column, transmission selector lever, other attachment
(08) Add-on equipment (e.g., CB, tape deck, air conditioner)
(09) Left instrument panel and below
(10) Center instrument panel and below
(11) Right instrument panel and below
(12) Glove compartment door
(13) Knee bolster
(14) Windshield including one or more of the following: front header, A-pillar, instrument panel, mirror, or steering assembly (driver side only)
(15) Windshield including one or more of the following: front header, A-pillar, instrument panel, or mirror (passenger side only)
(16) Other front object (specify):

LEFT SIDE

(20) Left side interior surface, excluding hardware or armrests
(21) Left side hardware or armrest
(22) Left A pillar
(23) Left B pillar
(24) Other left pillar (specify):

(25) Left side window glass or frame
(26) Left side window glass including one or more of the following: frame, window sill, A-pillar, B-pillar, or roof side rail
(27) Other left side object (specify):

RIGHT SIDE

(30) Right side interior surface, excluding hardware or armrests
(31) Right side hardware or armrest
(32) Right A pillar
(33) Right B pillar
(34) Other right pillar (specify):

(35) Right side window glass or frame
(36) Right side window glass including one or more of the following: frame, window sill, A-pillar, B-pillar, roof side rail
(37) Other right side object (specify):

INTERIOR

(40) Seat, back support
(41) Belt restraint webbing/buckle
(42) Belt restraint B-pillar attachment point
(43) Other restraint system component (specify):

(44) Head restraint system
(45) Air cushion
(46) Other occupants (specify):

(47) Interior loose objects
(48) Child safety seat (specify):

(49) Other interior object (specify):

ROOF

(50) Front header
(51) Rear header
(52) Roof left side rail
(53) Roof right side rail
(54) Roof or convertible top

FLOOR

(56) Floor including toe pan
(57) Floor or console mounted transmission lever, including console
(58) Parking brake handle
(59) Foot controls including parking brake

REAR

(60) Backlight (rear window)
(61) Backlight storage rack, door, etc.
(62) Other rear object (specify):

EXTERIOR OF OCCUPANT'S VEHICLE

(65) Hood
(66) Outside hardware (e.g., outside mirror, antenna)
(67) Other exterior surface or tires (specify):

(68) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE

(70) Front bumper
(71) Hood edge
(72) Other front of vehicle (specify):

(73) Hood
(74) Hood ornament
(75) Windshield, roof rail, A-pillar
(76) Side surface
(77) Side mirrors
(78) Other side protrusions (specify):

(79) Rear surface
(80) Undercarriage
(81) Tires and wheels
(82) Other exterior of other motor vehicle (specify):

(83) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT

(84) Ground
(85) Other vehicle or object (specify)

(86) Unknown vehicle or object

NONCONTACT INJURY

(90) Fire in vehicle
(91) Flying glass
(92) Other noncontact injury source (specify)

(97) Injured, unknown source

INJURY SOURCE CONFIDENCE LEVEL

(1) Certain
(2) Probable
(3) Possible
(9) Unknown

DIRECT/INDIRECT INJURY

(1) Direct contact injury
(2) Indirect contact injury
(3) Noncontact injury
(7) Injured, unknown source

OCCUPANT INJURY CLASSIFICATION

O.I.C. Body Region

(M) Abdomen
(Q) Ankle–foot
(A) Arm (upper)
(B) Back–thoracolumbar spine
(C) Chest
(E) Elbow
(F) Face
(R) Forearm
(H) Head–skull
(U) Injured, unknown region
(K) Knee
(L) Leg (lower)
(Y) Lower limb(s) (whole or unknown part)
(N) Neck–cervical spine
(P) Pelvic–hip
(S) Shoulder
(T) Thigh
(X) Upper limb(s) (whole or unknown part)
(O) Whole body
(W) Wrist–hand

Aspect of Injury

(A) Anterior–front
(C) Central
(I) Inferior–lower
(U) Injured, unknown aspect
(L) Left
(P) Posterior–back
(R) Right
(S) Superior–upper
(W) Whole region

Lesion

(A) Abrasion
(M) Amputation
(V) Avulsion
(B) Burn
(K) Concussion
(C) Contusion
(N) Crush
(G) Detachment, separation
(D) Dislocation
(F) Fracture
(Z) Fracture and dislocation
(U) Injured, unknown lesion
(L) Laceration
(O) Other
(P) Perforation, puncture
(R) Rupture
(S) Sprain
(T) Strain
(E) Total severance, transection

System/Organ

(W) All systems in region
(A) Arteries–veins
(B) Brain
(D) Digestive
(E) Ears
(O) Eye
(H) Heart
(U) Injured, unknown system
(I) Integumentary
(J) Joints
(K) Kidneys
(L) Liver
(M) Muscles
(N) Nervous system
(P) Pulmonary–lungs
(R) Respiratory
(S) Skeletal
(C) Spinal cord
(Q) Spleen
(T) Thyroid, other endocrine gland
(G) Urogenital
(V) Vertebrae

Abbreviated Injury Scale

(1) Minor injury
(2) Moderate injury
(3) Serious injury
(4) Severe injury
(5) Critical injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

OFFICIAL INJURY DATA – SKELETAL INJURIES

Indicate the *Location, Lesion, Detail* (size, depth, fracture type, head injury clinical signs and neurological deficits), and *Source* of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





OFFICIAL INJURY DATA – INTERNAL INJURIES

Indicate the *Location, Lesion, Detail* (size, depth, fracture type, head injury clinical signs and neurological deficits), and *Source* of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





PSU NUMBER 02

CASE NUMBER 051C

VEHICLE NUMBER 02

EXTERIOR VEHICLE FORM

THE FOLLOWING DATA IS NOT INCLUDED IN THIS CASE:

[✓] ENTIRE FORM

[ ] PAGE NUMBER (S) _____

PSU NUMBER 02

CASE NUMBER 051C

VEHICLE NUMBER 02

INTERIOR VEHICLE FORM

THE FOLLOWING DATA IS NOT INCLUDED IN THIS CASE:

[✓] ENTIRE FORM

[] PAGE NUMBER (S) _____

HH1091 2 If TREATMENT OA35 equals 0, 4 or 5, then WORKING DAYS LOST OA38
HH1092 should equal 00, 01, 97 or 99.

```
02051C00000011[redacted]381.12100000000000210150000002[redacted]8000000[redacted]88
02051C00010012[redacted]381.12100000000000102F0201L
02051C00020012[redacted]381.12100000000000102N3100N
02051C01000021 1.12 000000000854904004JT2SV16E1[redacted]99096550746102020230
0000040099799759 99 99999901
02051C01000031 1.12 0000000000231OOTYDDO3010212FRESO1
011024
02051C01000041 1.12 000000000981111000000266066869000000012202202122021O1
02051C01000042 1.12 0000000001314611214511114311316331312311313311314311112
211113211114218OO OO OO 00000057080
02051C01010051 1.12 0000000006226616011190000040411000930210000000000002320
7970000000009
02051C01010161 1.12 0000000002WRFS2572100
02051C01010261 1.12 0000000002FWLI1912300
02051C01010361 1.12 0000000002NPTM1923300
02051C01010461 1.12 0000000002CUCI1043100
02051C01010561 1.12 0000000002SLCI1203100
02051C01010661 1.12 0000000002HUCI1543108
02051C01010761 1.12 0000000002NUCI1979799
02051C01010861 1.12 0000000002BUCI1543108
02051C01010961 1.12 0000000002RRAI1573100
02051C01020051 1.12 0000010006217116021390000040411000930210000000000003420
0050000000002
02051C01020161 1.12 0000000003XRCI1113100
02051C01020261 1.12 0000000003WRLI1913300
02051C02000021 1.12 000000000864103504JM1BF222[redacted]99096559945102020221
9900000001804869 99 99999900
02051C02010051 1.12 0000000004029999911190000404999994999900000000000000000
0990000000000
02051C02020051 1.12 0000000001519999921390000404999994999900000000000000000
0970000000000
02051C8888888[redacted]381.12 000000000YY0202YYY0201Y0000000000000000000000000000000
00000000
02051C9999999[redacted]381.12 0000000000000000000000000000000000000000000000010000
00000000
```

EC0021 2 If INTRUDING COMPONENT IV48 equals 06, 07, 10, 11 or 13, then at
EC0022 least one (DEFORMATION LOCATION (EV07(n) should equal 9 or
EC0023 blank) or (EV07(n) should equal R or L and LONGITUDINAL LOCATION
EC0024 EV08(n) should equal D, P, Y, or Z)).

1988 NATIONAL ACCIDENT SAMPLING SYSTEM

ERROR SUMMARY SCREEN

App [redacted] 1988

CURRENT VERSION: 1.12

FORM NAME	NUMBER OF DOLLAR SIGNS	NUMBER OF LEVEL 1 ERRORS	NUMBER OF LEVEL 2 ERRORS	VERSION NUMBER CONSISTENT
Accident	0	0	0	Y
General Vehicle	0	0	0	Y
Vehicle Exterior	0	0	0	Y
Vehicle Interior	0	0	0	Y
Occupant Assessment	0	0	1	Y
Occupant Injury	0	0	0	Y
Total Inter Errors		0	1	
Total Case Errors	0	0	2	

U.S. Department of Transportation
National Highway Traffic Safety Administration

SLIDE INDEX

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Primary Sampling Unit Number 02 Case Number - Stratum 51C

Slide No.	Vehicle No.	Direction of Picture	Description of Slide Subject Matter
1-4	1	NB	Path of V1
5	1	SB	lookback
6-8	2	NB	Path of V1
9	2	SB	Lookback
10-21	1	-	Exterior
22-31	1	-	Interior

HS Form 434B
1/88

Slide No.	Vehicle No.	Direction of Picture	Description of Slide Subject Matter

PSU 02-051C (1988) #1

PSU 02-051C (1988) #2

PSU 02-051C (1988) #3

PSU 02-051C (1988) #4

PSU 02-051C (1988) #5

PSU 02-051C (1988) #6

PSU 02-051C (1988) #7

PSU 02-051C (1988) #8

PSU 02-051C (1988) #9

PSU 02-051C (1988) #10

PSU 02-051C (1988) #11

PSU 02-051C (1988) #12

PSU 02-051C (1988) #13

PSU 02-051C (1988) #14

PSU 02-051C (1988) #15

PSU 02-051C (1988) #16

PSU 02-051C (1988) #17

PSU 02-051C (1988) #18

PSU 02-051C (1988) #19

PSU 02-051C (1988) #20

PSU 02-051C (1988) #21

PSU 02-051C (1988) #22

PSU 02-051C (1988) #23

PSU 02-051C (1988) #24

PSU 02-051C (1988) #25

PSU 02-051C (1988) #26

PSU 02-051C (1988) #27

PSU 02-051C (1988) #28

PSU 02-051C (1988) #29

PSU 02-051C (1988) #30

PSU 02-051C (1988) #31